


Hampshire TSHARC™ - "mini" developers kit Quick View assembly diagram

Read This First!


When using supplied kit cables be sure that the communication cable connector is **label side UP** and match **white dots** from the cable connector to the board.

RS-232 communication / power connection



Txd transmit to board
Rxd transmit from board


PS/2 communication / power connection



STEP 1

Configure min jumper board or configure communication cable for direct connection to TSHARC mini. Connect communication cable. See users manual for direct cable connect detail.

Verify communication and Power connection before connecting to the controller.



4, 5 or 8 wire touch screen connection header

STEP 2

Connect user configurable touch screen cable to touch screen and controller. See users manual wiring diagrams for proper pin-out.

Break header to fit desired touch screen type.

Follow these steps:

- 1) Connect communication cable
- 2) Configure touch screen cable
- 3) Connect to computer
- 4) Connect power if necessary
- 5) Turn on computer
- 6) Install TSHARC drivers
- 7) Follow instructions on screen

Hampshire Company, Inc.
9055 N. 51st Street Unit H
Brown Deer, WI 53223
Main Phone: 414-355-4675
Main Fax: 414-355-4775

